



About Ridobiko:- Ridobiko is a two wheeler rental brand operating in 38+ cities with 1200+ vehicles listed on the platform. Ridobiko is now entering into two wheeler maintenance segment with 5+ years of expertise. Below are our charges: -

Routine service package (Per service)

- Bike (100 to 180 CC) service: ₹299
- Bike (more than 180 CC) service: ₹449
(Charges are excluding engine oil)

Routine service package (Yearly package)

- Bike (100 to 180 CC) service: ₹1249 (5 services per year)
- Bike (more than 180 CC) service: ₹1,799 (5 services per year)
(Charges are excluding engine oil)

Routine service includes:

- Air Filter Cleaning
- Clutch Cable inspect/ setting
- Accelerator Cable inspect/ setting
- Spark Plug Cleaning
- Brake Cable inspect/ setting
- Carburettor setting/ drain
- Front & rear disc pad cleaning/ setting
- All lights check (Headlight, tail lamp, indicator)
- Chain adjustment setting
- Disc brake oil top up if required
- Minor Fitting / nut bolts replacements

Minor Issue Type :

1. Spare Part: Visiting Charges Rs 250 + Spare MRP + Spare replacement labour
2. Issue Unknown: Rs 250, If any issue is not able to get identified on the spot the mechanic will pick up the bike to the workshop

Labour Charges

Service name	100 to 180cc	Above 180cc
Routing Servicing	299	449
Clutch Cable Replacement	50	80
Carburettor Drain/Settin	50	100
Carburettor Clean	100	200
Front Fork Oil or Seal change	150	250
Front Brake shoe setting	20	20
Rear Brake shoe setting	20	20
Front Brake shoe replacement	60	60
Rear Brake shoe replacement	50	80
Disc Brake pad replacement	75	150
Disc plate replacement	200	300
Master cylinder overhaul	150	150
Brakes Cleaning	60	60

Service name	100 to 180cc	Above 180cc
Disc Oil Top Up	40	40
Accelerator cable replacement	150	200
Speedometer cable change	50	100
Choke Cable Replacement	150	200
Brake Cable Replacement	250	250
Clutch Lever Replacement	50	50
Brake Lever Replacement	50	50
Tyre Replacement	80	100
Cone Set Replacement	250	250
Fork Bend Removal	350	350
Main Stand replacement	200	200
Lock set Replacement	150	150
Ignition Lock replacement	100	100
Chain sprocket replacement	150	200
Battery Replacement	50	50
Battery Charging	80	80
Headlight bulb replacement	50	50
Tail light bulb replacement	50	50
Indicator bulb or replacement	50	50
Half Engine Overhaul	750	1000
Full Engine Overhaul	1500	2000
Clutch Overhaul	350	350
Tappet Adjustment	100	100
Chain Cleaning/Overhaul	150	150
Kick Overhaul	150	

Contact number - 0124 427 7778

Website - <https://service.ridobiko.com/>

Email – contact@ridobiko.com

----- RIDBIKO SOLUTIONS PVT LTD -----